## HISTORIC AMERICAN ENGINEERING RECDRD

## INDEX TO PHOTOGRAPHS

ROCK ISLAND ARSENAL

Shop A (Building 102)

Rodman Avenue between Gillespie Avenue and First Street

Rock Island, Rock Island County, Illinois

Photographed by: Robert A. Ryan, J Ceronie, and Bruce A. Harms

DENNETT, MUESSIG, RYAN & ASSOCIATES, LTD. Iowa City, Iowa

January, February, March 1985

IL-20F-1	3/4 view showing N (front) & W elevations; looking SE. (Ceronie)
IL-20F-2	N front elevation, main block (Building 103 can be seen at the left of the view); looking SSW. (Harms)
IL-20F-3	General view of the S elevation, showing main block courtyard, and E & W wings; looking N. (Ceronie)
IL-20F-4	Detail view of central entry bay, N elevation of main block; looking S. (Harms)
IL-20F-5	Oetail view of typical ground level loading doorway, S elevation of E wing; looking N. (Ceronie)
IL-20F-6	General view of NE entry, first floor, showing original paneling; looking SSE. (Ryan)
IL-20F-7	General view of second floor, E wing; looking N. (Ryan)
IL-20F-B	Men's room, second floor of main block, showing original paneling built around a cast-iron column; looking S. (Ryan)
IL-20F-9	Original basement door and freight elevator, E wing; looking WNW. (Ceronie and Harms)
IL-20F-10	Detail view of pier at stairway, W wing (NW staircase); looking NNE. (Ceronie)
IL-20F-11	Attic, showing original office area in NE corner of main block;

looking NE. (Ceronie and Harms)

Rock Island Arsenal, Shop A (Building 102) HAER No. IL-20F Index to Photographs (Page 2)

- IL-20F-12 Detail view of typical gable end attic windows, main block; looking N. (Ceronie and Harms)
- IL-20F-13 Photograph of a photograph in possession of Rock Island Arsenal Historical Office. NORTH ELEVATION IN UNALTERED CONDITION. TAKEN ABOUT 1907.
- IL-20F-14 Photograph of line drawing in possession of Engineering Plans and Services Oivision, Rock Island Arsenal. ELEVATIONS AND SECTIONS OF CAST IRON COLUMNS, UNDATED.